

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3655	DATE	October 28,2015
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to an inappropriate installation work at the factory, the lip seal of the brake booster may have been installed without grease. As a result, the lip seal may be turned inward due to the increased friction resistance causing air leak in the booster and, in the worst case scenario, stopping distance may be lengthened due to the increased brake pedal force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-GG2W	「OUTLANDER PHEV」	2013	1,682
		TOTAL	1,682