

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3664	DATE	October 28,2015
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate installation operation in which the quick connector of the fuel hose was connected to the fuel pipe, the quick connector may not have been installed properly in some vehicles. As a result, the fuel may leak from the portion where the quick connector is connected to the fuel pipe.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-GG2W	「OUTLANDER PHEV」	2015	1,901
		TOTAL	1,901