

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2246	DATE	October 21, 2015
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Due to poor manufacturing of fuel pump, plating finish for internal parts would be peeled off and remained as foreign object in the component; which, might be caught in impeller and fuel pump stops working. In the worst case, engine stalls during driving and impossible to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8VCJSF	A3 SB 1.8 TFSI Quattro	2014	31
ABA-8VCJSL	A3 Sedan 1.8 TFSI Quattro		68
ABA-8VCJXF	S3 SB		21
ABA-8VCJXL	S3 Sedan		48
DBA-8VCPT	A3 SB 1.4 TFSI COD		32
DBA-8VCPTL	A3 Sedan 1.4 TFSI COD		39
DBA-8VCXS	A3 SB 1.4 TFSI		194
DBA-8VCXSL	A3 Sedan 1.4 TFSI		220
		Total	653