

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3657	DATE	Oct.21.2015
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	Due to insufficient strength of the body panel where the hood lock is installed, if the vehicle is operated at high speed with the main lock disengaged, the body panel where the sub lock component is mounted could become deformed by wind pressure. If this occurs, the sub lock could disengage and the hood may open while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GRS210	[CROWN]	2012-2015	17,516
DBA-GRS211		2012-2015	6,185
DBA-GRS214		2012-2015	4,850
DAA-AWS210		2012-2015	95,313
DAA-AWS211		2014-2015	5,663
DAA-AWS215		2014-2015	1,039
DAA-GWS214		2013-2015	9,976
		TOTAL	140,542