

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3654	DATE	October 16,2015
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In both side of the seat belt at 3 rd row seat, some of the bolts may have been tightened with the torque which is less than the specification due to inappropriate designation of the tightening torque of the shoulder anchor bolt. As a result, if use continues under this condition, the seat belt may not properly restrain the passengers due to the loosened bolts on the subject.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-CV5W	「DELICA」	2015	269
DBA-CV2W		2015	233
LDA-CV1W		2015	888
		TOTAL	1,390