

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 6 6 0	DATE	O c t . 9 . 2 0 1 5
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	During the repair work for the external flaws of the handle peripheral components, due to inappropriate reassembly work that was done for the handle holder, the tightening torque for some of the bolts became insufficient. Therefore, if it is used continuously, the said bolts will be loosened, and in the worst case scenario, the handle may not be securely fixed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
J B K - R G 1 0 J	M T 2 5 0	2 0 1 5	4 7
E B L - R H 0 7 J	M T 3 2 0	2 0 1 5	1 1
		TOTAL	5 8