VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

	-		Domestic vemeres
CAMPAIGN No.	3652	DATE	Oct. 8, 2015
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Due to a improper manufacture program of the fuse box, some terminals of blower motor have been assembled reversely. In such fuse boxes, it is possible that the terminals are fixed insufficiently and rubbed against each other, leading to generation of insulating material. In the worst case, defroster may not operate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA600S	TANTO	2015	2,421
DBA-LA610S	TANTO		531
DBA-LA150S	MOVE	2015	736
DBA-LA160S	MOVE		170
DBA-LA150F	CTELL A	2015	26
DBA-LA160F	STELLA		16
		TOTAL	3,900