

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3648	DATE	2 October, 2015
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	<p>Regarding the fire ladder trucks (listed below), the welding condition between the rear axle torque rod mounting bracket and the underside of the frame is inappropriate; thus the welded section may crack/break when braking stress is repeatedly applied. If the vehicle is operated under this condition, the crack may aggravate, and in the worst case, the torque rod mounting bracket may fall apart at the welded section and may cause the vehicle to become inoperable.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FJ483LN	Nissan Diesel -	2006—2008	2
FJ550LN	Nissan Diesel -	1997—1999	10
FJ552LN	Nissan Diesel -	2000—2006	34
		TOTAL	46