

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2241	DATE	October.1. 2015
MANUFACTURER	HONDA CANADA INC.		
DESCRIPTION OF DEFECT	As regards certain driver's SRS airbag inflators, abnormal rise in internal pressure of the inflator can occur in the event of the airbag deployment whereby the container of the inflator could break and scatter the inflator component parts around, causing injury to the vehicle occupant.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-RL1	「LAGREAT」	2001	1
CBA-YD1	「MDX」	2005	1
		TOTAL	2