

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 6 4 4	DATE	Oct.1.2015
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to an inappropriate location for the connection of negative pressure piping on the brake booster that is inside the compartment, the driver's foot may be knocked unconsciously against the connection in certain posture of the driver. If the excessive force operates in this condition, the connection may be dislocated occasionally, As a result, the negative pressure will not be supplied and the braking distance may increase due to the insufficient brake power assist.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-VR2E26	N I S S A N NV350 CARAVAN	2012 ~ 2013	10,860
LDF-VW2E26			7,084
LDF-VW6E26			5,205
CBF-CS4E26			1,975
LDF-CW8E26			1,353
LDF-CW4E26			702
CBA-KS2E26			1,154
CBA-KS4E26			373
CBF-DS4E26			43
LDF-DW4E26			82
CBF-JVR2E26	I S U Z U C O M O		74
LDF-JVW2E26			179
LDF-JVW6E26			143
CBF-JCS4E26			2
LDF-JCW8E26			10
LDF-JCW4E26			15
CBF-JDS4E26			1
		TOTAL	29,255