

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2255	DATE	Nov. 27, 2015
MANUFACTURER	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	There is a battery cable connection stud bolt box at the engine bulkhead. The nut, which secures the cable end, may come loose due to improper tightening torque. With this condition, it causes a loose electrical connection to result in the engine being unable to start. Also the cable connection stud box is overheated by a loose electrical connection. In the worst case, the overheating could lead to a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-BFCKH	Continental GT	2012	86
ABA-BFCVA	Continental GT	2013 – 2014	52
	Continental GT Speed	2013 – 2014	51
ABA-BSCKH	Continental Flying Spur Speed	2012 – 2013	25
ABA-BCCKH	Continental Supersports	2012	2
ABA-BECVA	Flying Spur W12	2014	171
ABA-BFCMM	Continental GT V8	2013 – 2014	211
ABA-BGCKH	Continental GTC	2012	8
ABA-BGCVA	GT Speed Convertible	2014	11
	Continental GTC	2013 – 2014	19
ABA-BGCMM	Continental GTC V8	2012 – 2014	46
ABA-BFCYC	Continental GT V8	2015	3
-BCCKH-	Continental GT	2012	3
-BFCKH-	Continental GT	2012	6
	Continental GTC	2012	1
	Continental GT V8	2013	2
FUMEI	Continental GT Speed	2013	1
-BECMM-	Flying Spur V8	2014	2
FUMEI	Flying Spur W12	2014	3
-BFCMM-	Continental GT V8	2014	1
-BGCMM-	Continental GTC V8	2014	1
TOTAL			705