

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3705	DATE	November 27, 2015
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the fuel filter equipped on the captioned vehicles, because the clamp surface of the drain plug is not secured its flatness, the gasket may deform or crack by pressure when the drain plug is tightened with the excessive torque at manufacturing. Therefore, fuel may leak in case of continuous use or the loosing/ re-tightening the drain plug at regular maintenance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-DJ5AS	Mazda 「DEMIO」	2015	6,765
LDA-DJ5FS		2015	41,437
LDA-DK5AW	Mazda 「CX-3」	2015	7,467
LDA-DK5FW		205	18,681
		Total	74,350