

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3704	DATE	November 27, 2015
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the engine auxiliary belt equipped with the captioned vehicles, the strength of the belt may deteriorate because the tension of the core wire is not equalized at the belt manufacturing. Therefore, the belt may break due to engine operation, the alternator and the water pump may stop operating, and malfunction indicator light may illuminate. In the worst case, the engine may stop, resulting in no restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-DJ5AS	Mazda 「DEMIO」	2015	5,837
LDA-DJ5FS		2015	36,504
LDA-DK5AW	Mazda 「CX-3」	2015	6,279
LDA-DK5FW		205	15,148
		Total	63,768