

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2274	DATE	November.26. 2015
MANUFACTURER	HONDA OF THE UK MFG., LTD.		
DESCRIPTION OF DEFECT	During the engine side mount installation, protective tube of electrical wires (engine room wire harness) can be damaged by the tightening bolt. Due to this, a sheath of an electrical wire can be torn due to vibration while driving, causing a short circuit. If this occurs, the right head light, front fog light, position light or brake light may not come on or the horn may not sound.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FN2	「CIVIC」	2009	1
		TOTAL	1