

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3701	DATE	November.26. 2015
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>The noise suppression resistor, which removes electrical noise in the ignition coil, has a structural fault and the resistor may be open-circuited at its terminal due to arc discharge induced by energization at the ignition. Should this happen, the ignition coil output would become insufficient whereby the engine could malfunction, when the engine warning light would come on. Alternatively the noise produced at the ignition would render the fuel injection system uncontrollable whereby the engine could stall.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-JH1	「N-WGN」	2014	28
DBA-GK3	「FIT」		2
		TOTAL	30