

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3696	DATE	Nov. 25, 2015
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the inflator of the passenger side frontal airbag, there is a possibility that the inflator body could rupture and scatter, potentially increasing the risk of fire or injury to the occupant during the deployment of the airbag.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-KSP90	[VITZ]	2005-2008	128,650
DBA-NCP91		2005-2008	31,093
CBA-NCP95		2005-2008	40,202
DBA-SCP90		2005-2008	175,914
TA-AZR60G CBA-AZR60G DBA-AZR60G	[NOAH] [VOXY]	2004-2007	336,122
TA-AZR65G CBA-AZR65G DBA-AZR65G		2004-2007	77,024
UA-ANH10W CBA-ANH10W DBA-ANH10W	[ALPHARD G] [ALPHARD V]	2004-2008	131,518
UA-ANH15W CBA-ANH15W DBA-ANH15W		2004-2008	28,364

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-MNH10W CBA-MNH10W	[ALPHARD G] [ALPHARD V]	2004-2008	59,245
TA-MNH15W CBA-MNH15W		2004-2008	26,868
ZA-ATH10W CAA-ATH10W DAA-ATH10W	[ALPHARD HYBRID]	2004-2008	17,609
UB-NCP50V CBE-NCP50V	[PROBOX]	2004-2008	29,302
UP-NCP52V DFE-NCP52V		2004-2008	493
UB-NCP51V CBE-NCP51V	[PROBOX] [SUCCEED]	2004-2008	81,115
UB-NCP55V CBE-NCP55V		2004-2008	29,578
UA-NCP58G CBA-NCP58G		2004-2008	26,059
UA-NCP59G CBA-NCP59G		2004-2008	7,978
KP-NLP51V		2004-2007	5,984
UA-NZE121 CBA-NZE121 DBA-NZE121	[COROLLA] [COROLLA RUNX]	2004-2006	111,055
UA-NZE124 CBA-NZE124	[ALLEX]	2004-2006	15,285
UA-ZZE122 CBA-ZZE122		2004-2006	11,920
UA-ZZE124 CBA-ZZE124		2004-2006	2,320
KE-CE121	[COROLLA]	2004	71
UA-NZE120 CBA-NZE120		2004-2006	5,193

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-ZZE123	[COROLLA RUNX] [ALLEX]	2004-2006	2,717
KE-CE121G	[COROLLA FIELDER]	2004	28
UA-NZE121G CBA-NZE121G DBA-NZE121G		2004-2006	67,689
UA-NZE124G CBA-NZE124G		2004-2006	11,024
TA-ZZE122G UA-ZZE122G CBA-ZZE122G		2004-2006	17,399
TA-ZZE123G		2004-2006	1,528
UA-ZZE124G CBA-ZZE124G		2004-2006	4,435
DBA-KSP92		[BELTA]	2005-2008
CBA-NCP96	2005-2008		7,019
DBA-SCP92	2005-2008		35,230
UA-ACM21W CBA-ACM21W DBA-ACM21W	[IPSUM]	2004-2008	26,811
UA-ACM26W CBA-ACM26W DBA-ACM26W		2004-2008	7,013
TA-JZX115	[MARK II]	2004	211

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-GX110	[MARK II] [VEROSSA]	2004	10,231
TA-GX115		2004	1,336
GH-JZX110 TA-JZX110		2004	3,527
TA-GX110W	[MARK II BLIT]	2004-2007	5,912
TA-GX115W		2004-2007	1,213
GH-JZX110W TA-JZX110W		2004-2007	2,665
TA-JZX115W		2004-2007	606
TA-JCG10	[BREVIS]	2004-2007	3,920
TA-JCG11		2004-2007	1,143
TA-JCG15		2004-2007	644
UA-NCP70 CBA-NCP70	[WILL CYPHA]	2004-2005	4,159
UA-NCP75 CBA-NCP75		2004-2005	686
TA-ACM10G	[GAIA]	2004	2,020
TA-ACM15G		2004	582
KH-CXM10G		2004	16

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-ACT10	[OPA]	2004-2005	158
CBA-ZCT10		2004-2005	1,813
UA-ZCT15 CBA-ZCT15		2004-2005	574
TA-NZE127 UA-NZE127	[WILL VS]	2004	64
TA-ZZE127		2004	50
TA-ZZE128		2004	43
TA-ZZE129		2004	20
		TOTAL	1,612,670

(Note) This report is filed to change the remedies of the recalls filed on May 13th, 2015 and June 25th, 2015, which recall numbers are 3563 and 3592 respectively.

The above vehicle range includes vehicles not affected from this recall, such as vehicles of which the inflator has already been replaced with new one in the previous recalls, etc.