

Vehicle Safety/Pollution Recall Campaign In Japan

Domestic/Import Vehicles

|   |  |      |                     |
|---|--|------|---------------------|
| Campaign No.  | Gai 2276   | Date | N o v 2 0 , 2 0 1 5 |
| Name(s) of person or company  | Tesla Motors Netherland BV<br>Managing Director : Todd Andrew Maron<br>Director of Homologation : Suraj Nagaraj<br>Country : United states<br>Manufacturer :<br>Tesla Motors, Inc.<br>Phone number: 0120-975-214 |      |                     |
| Condition of structure and system acknowledged as non-compliant condition, and its root cause | Some Model S vehicles might have been manufactured with the pre-tensioner(s) for the 1 <sup>st</sup> row seat belts installed incorrectly. In worst case, seat belt(s) are not able to secure passengers.        |      |                     |

| Type       | Commercial Name | Model Year Recalled   | Number of affected vehicles |
|------------|-----------------|---|-----------------------------|
| ZAA-SL1S   | Model S         | 5YJSB6H14EFP46026 -<br>5YJSB7H16FF085994<br>2014/10/31 - 2015/06/16 | 113                         |
| ZAA-SL1SA  |                 | 5YJSB3H10EFS37128 -<br>5YJSB7H18FF093434<br>2014/07/19 - 2015/09/21 | 144                         |
| ZAA-SL1S2  |                 | 5YJSB6H13EFP46325 -<br>5YJSB7H1XEFP64410<br>2014/10/31 - 2014/12/08 | 21                          |
| ZAA-SL1S2A |                 | 5YJSB3H11EFP45799 -<br>5YJSB7H18FFP66108<br>2014/07/04 - 2015/02/10 | 162                         |
| ZAA-SL2S   |                 | 5YJSB7H28FFP78879 -<br>5YJSB7S26FF100849<br>2015/07/28 - 2015/10/16 | 23                          |
| ZAA-SL2SA  |                 | 5YJSB7H25FFP77687 -<br>5YJSB7S20FF100863<br>2015/06/29 - 2015/10/16 | 36                          |
| ZAA-SL2S2  |                 | 5YJSB7H43FFP78788 -<br>5YJSB7H40FF099643<br>2015/07/28 - 2015/10/03 | 9                           |

|             |   |     |
|-------------|---|-----|
| ZAA-SL2S2A  | 5YJSB7H46FFR00009 -<br>5YJSB7H41FF097142<br>2015/05/11 - 2015/11/13 | 77  |
| ZAA-SWL1S   | 5YJSB7S16FF098706 -<br>5YJSB7E19FF112951<br>2015/09/21 - 2015/11/20 | 11  |
| ZAA-SWL1SA  | 5YJSB7S14FF098705 -<br>5YJSB7E19FF109449<br>2015/09/21 - 2015/11/20 | 12  |
| ZAA-SWL2S   | 5YJSB7E20FF102429 -<br>5YJSB7E22FF114582<br>2015/10/16 - 2015/11/20 | 19  |
| ZAA-SWL2SA  | 5YJSB7E28FF103411 -<br>5YJSB7E28FF113341<br>2015/10/16 - 2015/11/20 | 26  |
| ZAA-SWL2S2  | 5YJSB7E47FF093049 -<br>5YJSB7E49FF092145<br>2015/11/13 - 2015/11/13 | 2   |
| ZAA-SWL2S2A | 5YJSB7E48FF093044 -<br>5YJSB7E42FF099647<br>2015/09/21 - 2015/11/20 | 26  |
|             | Total   | 681 |