

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3694	DATE	November 19 ,2015
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Some dump trucks and concrete mixer trucks may be failing to satisfy the safety standards because of their bracket for front underrun protection. As the shape of the bracket is improper, the pitman arm and drug link boot interfere with the bracket when the steering wheel is turned clockwise.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
TKG-FRR90S1 TKG-FRR90S2	[FORWARD]	2014-2015	1,986
TOTAL			1,986

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
TKG-FRR90S2	[FORWARD]	2015-2015	5
TOTAL			5