

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3676	DATE	Nov.18.2015
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the fuel pump of the subject hybrid vehicles, due to improper setting of the pump motor revolution, the motor brush could vibrate and may wear prematurely. If this occurs, the fuel will not be supplied along with illumination of warning lights, causing the vehicle to not be operated by the engine power, resulting in the vehicle becoming inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-AZK10	[SAI]	2009-2013	60,836
DAA-ANF10	[HS250h]		33,358
		TOTAL	94,194