

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	3667	DATE	November 4, 2015
MANUFACTURER	KOBELCO CRANES CO.,LTD		
DESCRIPTION OF DEFECT	<p>On the wheel crane RK250-7, the route of the electric wire for the starter motor is improper. So the electric wire and the pipe(s) of hydraulic line(s) is/are interfered. Therefore, it might cause damage on insulation of the electric wire.</p> <p>As the result of it, it might make the spark when the electric wire(s) and the hydraulic piping is/are directly touched, And cable break or damage on hydraulic piping might occur. Then, finally, there are the cause of defects what is oil leakage and/or is engine start failure.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-EE02	RK250-7	2008-2013	277 units
TOTAL			277