

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3716	DATE	Dec. 18, 2015
MANUFACTURER	SHO—SHIN Co, Ltd.		
DESCRIPTION OF DEFECT	In the exhaust pipe of the crop—dusting vehicles, for routing of the exhaust pipe is inappropriate, and continue to receive repeat the vibration from the engine, and the mounting stay of the exhaust pipe, that the cracks in the welding portin of the exhaust pipe and the muffler is there. Therefore, continuing to use as is, a crack region is broken, in the worst case, during running, the exhaust pipe or muffler is likely to fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDN—G8	「3S—FSC1061」	2010—2014	92
	「SSA—V1021CL」	2010—2014	81
	「3S—FSC1061L」	2010—2014	52
KDN—H2	「3S—C1061」	2011—2014	34
	「3S—FS1061」	2011—2014	37
TOTAL			296