

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	3724	DATE	Dec.17, 2015
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Due to improper heat treatment of the tappet and cylinder head assembly process of the engine, contamination between the tappet and camshaft may cause abnormal wear to tappet and cam, and noises may occur from the engine. In worse case, it may cause the engine to stall while riding.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBK-CJ45A	SKYWAVE	2012~2013	493
JBK-CJ46A		2012~2013	1,758
EBL-CP52A		2013	540
EBL-VK58A	GLADIUS	2012~2013	422
EBL-VP56A	V Strom	2013~2014	1,262
EBL-GR7NA	GSR750	2013~2014	1,833
EBL-GW72A	Bandit 1250	2012~2014	470
		TOTAL	6,778