

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3723	DATE	Dec.17, 2015
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to use improper material of head light bulb filament in production process may cause decreasing to its strength.</p> <p>With continued use in this condition, bulb filament may break out by vehicle vibration.</p> <p>In worst case, broken part of filament touch to earth wire in bulb, causing fuse break out lead to engine stall.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBJ-CE47A	Address 110	2015	8,361
		TOTAL	8,361