

**VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN**

**Domestic Vehicles**

<b>CAMPAIGN No.</b>	<b>3718</b>	<b>DATE</b>	<b>Dec 15, 2015</b>
<b>MANUFACTURER</b>	<b>SUZUKI MOTOR CORPORATION</b>		
<b>DESCRIPTION OF DEFECT</b>	<p>Due to an inappropriate instruction, the Fuel Tank Breather Hose was improperly assembled and may be kinked.</p> <p>If Fuel Tank Breather Hose is kinked, prevent the Fuel Tank from proper venting and fuel tank internal pressure becomes abnormally causing deformation of the Fuel Tank.</p> <p>In worse case, this can lead to damage and causing fuel leak from the Fuel Tank.</p>		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLE</b>
<b>EBL-VK58A</b>	<b>GLADIUS</b>	<b>2014</b>	<b>62</b>
		<b>TOTAL</b>	<b>62</b>