

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3710	DATE	December 11.2015
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	<p>Deformation of stopper stay of brake pedal When depress brake pedal and release the brake pedal, the brake pedal returns original position by spring force. Due to insufficient strength of stopper stay, the stopper stay will deform after repeat brake pedal operation. If the brake pedal deforms, hole alignment between right brake pedal and left brake pedal will be out of order. In this case, the connecting pin will not go through holes between right brake pedal and left brake pedal. This means that right brake pedal and left brake pedal cannot connect.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDN-65J	「EG58」	2012-2014	60
	「EG65」	2012-2014	504
-	「EG76」	2009-2014	133
	「EG83」	2009-2014	234
KPD-83B	「EG76」	2009-2014	360
	「EG83」	2009-2014	810
-	「EG765」	2004-2009	228
	「EG765」	2005-2008	120
-	「EG775」	2004-2009	305
	「EG782」	2004-2009	459
SB-82B	「EG775」	2005-2009	213
	「EG782」	2005-2009	409
TOTAL			3835