

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3721	DATE	December 10, 2015
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the clutch reserve hose for manual transmission vehicle, O-rings at the joint may be made of inappropriate material. Therefore, a long term use causes cracks in the O-ring and oil leakage, and in the worst case, the gear cannot shift		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-DJ3FS	Mazda 「DEMIO」	2015	84
LDA-DJ5FS		2015	11
		Total	95