

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 7 1 7	DATE	Dec.10.2015
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Due to inappropriate circuit for the turn signal lamp in the BCM (body control module) controlling the operation of the electrical components, the IC for the turn signal lamp in the BCM may break by the static electricity charged on the front combination lamp and the turn signal lamps will remain on. If the lamps continue to remain on, the BCM may heat up and be burned, in an extreme case, it may lead to vehicle fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-N17	N I S S A N M T L A T I O	2 0 1 4 ~ 2 0 1 5	1, 3 4 3
		TOTAL	1, 3 4 3