

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3697	DATE	Dec. 3, 2015
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Due to an inappropriate fitting operation of the shift cable to the shift lever in the continuously variable transmission, the shift cable may have been insufficiently connected. If a vehicle is used continuously in this condition, the shift cable may become detached from the shift lever to cause the gear to remain in a different range from the shift lever position. In the worst case, the vehicle concerned may start moving accidentally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA600S	TANTO	2013-2014	107,118
DBA-LA610S			21,748
		TOTAL	128,866