

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3740	DATE	Jan 29,2016
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>On some wheel crane power transmission devices, the spacer and flange facing surfaces may wear prematurely with long-term travel resulting in reduced flange installation bolt axle force and loosening due to insufficient design evaluation of the torque converter spline.</p> <p>With continued use of the vehicle the bolt may be lost, in the worst case, leading to looseness of the flange and a loss of travel functions due to a power transmission failure.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SD-T002	TADANO 「CREVO 160」 「GR-180N-1」	2004-2008	301
JDS-T006	TADANO 「GR-160N-2」 「GR-120NDW-2」	2008-2012	214
SD-EW04	KOBELCO 「RK160-5」	2004-2008	98
SD-EW05			
JDS-EW06	KOBELCO 「RK160-6」	2008-2011	32
		TOTAL	645