

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicle

CAMPAIGN No.	GAI-2296	DATE	Jan 29,2016
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	As the inner boom cylinder stow position is unspecified in the Operators Manual for cranes, depending on the cylinder stow position, the axle load exceeds the load weight designated in standard relaxations based on a provision of article 55 of the national safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FAUN	ATF90G-4	2014-2015	①46 ②25
		TOTAL	46