

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 7 3 8	DATE	J a n . 2 6 . 2 0 1 6
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>As there was not much space between the primary chain and the oil nozzle in the motor, the primary chain may stretch out and touch the oil nozzle.</p> <p>Therefore, if it is used continuously, the oil nozzle may fall into the motor and get caught in the space between the crank case and the crank shaft, etc. In the worst case scenario, the engine may be locked while running and not be able to be restarted.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-RP17J	XJR1300	2006~2015	2,661
	XJR1300L	2011	172
		TOTAL	2,833