

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3737	DATE	Jan.26 2016
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	There may have the clamp bolts for the tie rod's ends tighten insufficiently with regard to the steering device. Therefore, when you continue to use it with this condition, threads of the tie rod's ends may be damaged, then, at worst, it may not be possible to steer the vehicle correctly with the tie rod came off from the ends.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
JD-KRC001	KR - 20H	2005~2008	52	
			TOTAL	52