

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	3730	DATE	January 20, 2016
MANUFACTURE	SUMITOMO NACCO MATERIALS HANDLING CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	When the LPG tank bracket was expanded to side direction by loosening nob bolt for inspection etc., there was one side of rear reflector was hidden by it due to inappropriate design. It means not conform to safety standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SG1HL	FL15PX	2006 ~ 2008	9
SG1H	FT09PX FT10PX FT14PX FT15PX FT18PX FT20PX	2005 ~ 2008	65
SG2GL	FL25PX	2007	1
SG2G	FT20PX FT25PX	2005 ~ 2008	61
SG3	FT30PX	2007	1
G1K改	FL15PX FT15PX	2005 ~ 2008	4
G3G改	FT30PX FT35PX	2006 ~ 2007	4
EBT-SG1JL	FL10PXI FL15PXI FL18PXI FL20PXI	2008 ~ 2014	81
EBT-SG2HL	FL20PXI FL25PXI	2008 ~ 2014	73
SG3AL	FL30PXI	2010 ~ 2013	3

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBT-G2K改	FL20PXI FL25PXI	2008 ~ 2012	4
EBT-G3G改	FL30PXI	2009 ~ 2013	3
EBT-SG1KT	FT09PXII FT15PXII FT18PXII	2014 ~ 2015	9
EBT-SG2JT	FT20PXII FT25PXII	2014 ~ 2015	2
EBT-G3H改	FT30PXII	2015	1
		TOTAL	321