

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3733	DATE	Jan. 15, 2015
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	A damaged center pillar reinforcement, caused by an inappropriate manufacturing process, may be installed in a vehicle. Therefore, it is possible that those vehicles may not comply with side impact standard provided in article 18 of Japanese Safety Standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GJ3	「IMPREZA」	2015	1
DBA-GP2		2015	1
DBA-GP3		2015	4
DBA-GP6		2015	1
DBA-GP7		2015	5
DBA-GPE		2015	6
DBA-VM4		「LEVORG」	2015
DBA-VMG	2015		2
CBA-VAB	「WRX」	2015	2
DBA-VAG		2015	2
		TOTAL	28