

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3780	DATE	February 25, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the power window switch at the driver side door, due to inappropriate inner structure, abnormal current may flow inside the switch circuit board when a lot of liquid intrudes into the inside the switch. Therefore, heat generation and dissolved loss occur at this area, in the worst case, resulting in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E-SGEW GF-SGEW GH-SGEW	Mazda 「BONGO FRIENDEE」	1995-2002	6,929
E-SGE3 GF-SGE3 GH-SGE3		1997-2002	530
E-SG5W GF-SG5W		1995-2002	5,381
KD-SGL3 KH-SGL3		1995-2002	3,040
KD-SGL5 KH-SGL5		1995-2002	6,138
KD-SGLR KH-SGLR		1995-2002	8,228
KD-SGLW KH-SGLW		1995-2002	8,508
E-SGEWF GF-SGEWF	Ford 「FREDA」	1995-2001	4,103
E-SGE3F GF-SGE3F		1997-2001	127
E-SG5WF GF-SG5WF		1995-2001	4,299
KD-SGL3F KH-SGL3F		1995-2000	1,945
KD-SGL5F KH-SGL5F		1995-2001	2,794
KD-SGLRF KH-SGLRF		1995-2001	4,652
KD-SGLWF KH-SGLWF		1995-2000	5,725
	TOTAL		62,399