

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2298	DATE	Feb.24, 2016
MANUFACTURER	SUZUKI MOTOR CORPORATION (Japanese Importer : ITOCHU Automobile Corporation)		
DESCRIPTION OF DEFECT	<p>Due to an inappropriate instruction, the Fuel Tank Breather Hose was improperly assembled and may be kinked.</p> <p>If Fuel Tank Breather Hose is kinked, prevent the Fuel Tank from proper venting and fuel tank internal pressure becomes abnormally causing deformation of the Fuel Tank.</p> <p>In worse case, this can lead to damage and causing fuel leak from the Fuel Tank.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CX112	GLADIUS	2013	20
		2015	10
		TOTAL	30