

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3778	DATE	Feb 23, 2016
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p align="center"> Due to improper tightening of fixing bolts for intake pipe and cylinder head, these bolts may become loose during riding and cause sucking air into engine from between the intake pipe and cylinder head. In the worst case, engine rpm will increase without any intention. </p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBH-CA4AA	Let's	2014	10
		TOTAL	10