

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3 7 7 7	DATE	F e b . 2 3 . 2 0 1 6
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to an inappropriate machining of the part which regulates the amount of airflow in the throttle body of the motor, the valve which regulates the amount of airflow does not close while the cooling water is at the high temperature, and because of that, an excess amount of air may be supplied to the engine. Therefore, even though the throttle is fully closed while running, the engine rotation may not go down to the idling engine speed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-S J 1 2 J	XP500A TMAX	2 0 1 6	2
		TOTAL	2