

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3776	DATE	February 19,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In certain type of inflators for driver's side airbag, the inflators will be replaced as a preventative measure since the body of the inflators may rupture at the time of the deployment of the airbag although the root cause has not been identified.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2012~2014	13,540
DBA-CV2W		2011~2014	8,905
DBA-CV4W		2009~2011	8,325
DBA-CV5W		2007~2014	97,111
CBA-V83W	「PAJERO」	2006~2009	1,461
DBA-V83W		2009~2014	714
CBA-V87W		2006~2011	916
ADC-V88W		2009~2010	170
LDA-V88W		2010~2014	804
CBA-V93W		2006~2009	6,582
DBA-V93W		2009~2014	2,794
CBA-V97W		2006~2012	3,239
ADC-V98W		2008~2010	1,742
LDA-V98W		2010~2014	6,375
		TOTAL	152,678