

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3770	DATE	February 19, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On inflators installed in frontal driver frontal air bag modules, as part of the parts supplier's continuing investigation of returned parts from fields, excessive internal pressure of the inflator case, which may potentially lead to rupture, was found. Therefore, although the root cause has not been identified, inflators of the same type which had been manufactured till a certain period are replaced with the new ones for preventive measures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-WH33F	Mazda 「Titan」	2004	10
KK-WH33G		2004	39
KK-WH35D		2004	153
KK-WH35T		2004	90
KK-WH38H		2004	10
KK-WH3HD		2004	94
KK-WH3HH		2004	18
KK-WH63F		2004	6
KK-WH63G		2004	37
KK-WH63H		2004	73
KK-WH65D		2004	33
KK-WH65G		2004	4
KK-WH65H		2004	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-WH65T	Mazda 「Titan」	2004	16
KK-WH68G		2004	11
KK-WH68H		2004	14
KK-WH68K		2004	18
KK-WH69G		2004	27
KK-WH69H		2004	35
KK-WH6HD		2004	132
KK-WH6HH		2004	31
KK-WHF3F		2004	19
KK-WHF3G		2004	47
KK-WHF5D		2004	202
KK-WHF5G		2004	2
KK-WHF5T		2004	222
KK-WHS5T		2004	196
			Total