

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 7 6 4	DATE	Feb.18.2016
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the emergency vehicles, due to inappropriate waterproofing of the harness in the driver's side step, the water which entered the compartment by the snow which attached to soles of shoes flows to the step portion and it collects in the protective cover of the harness and the joint portion of the flooded harness corrodes and the harness may be disconnected. For that reason, if the vehicle continues to be driven in this condition, in an extreme case, the engine might not be able to start.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
TC-FPWGE50 KAI ABF-FPWGE50 KAI CBF-FPWGE50 KAI	N I S S A N P A R A M E D I C	2 0 0 3 ~ 2 0 1 5	1, 2 8 7
TC-FPGE50 KAI ABF-FPGE50 KAI CBF-FPGE50 KAI			1 7 3
GE-FLWGE50 KAI		1 9 9 9 ~ 2 0 0 3	3 1 9
GE-FLGE50 KAI	9 0		
E-ALWE50 KAI	N I S S A N C A R A V A N E L G R A N D	1 9 9 8 ~ 1 9 9 9	4 8
E-ALE50 KAI			1 4
GE-JFLWGE50 KAI	I S U Z U S U P E R M E D I C I I	1 9 9 9	1
GE-JFLGE50 KAI		1 9 9 9 ~ 2 0 0 1	1 2
E-JALE50 KAI	I S U Z U F A R G O F I L L Y	1 9 9 9	2
		TOTAL	1, 9 4 6