VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2312	DATE	February.18. 2016	
MANUFACTURER	Thai Honda Manufacturing Co., Ltd.			
DESCRIPTION OF DEFECT	In the rear brake piping, the bolts for fastening the rear brake hose and the rear brake pipe together may have been undertightened because of inadequacies in the			
	bolt tightening process. Such bolts can, whilst in use, come loose and cause brake fluid to leak and could, in the very worst case, lead to loss of the rear brain effectiveness.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
JBK-MF12	「FORZA Si」	2013	2,568
		TOTAL	2,568