

CAMPAIGN No.	3766	DATE	FEB.17. 2016		
MANUFACTURER	HANTA MACHINERY CO. LTD.				
DESCRIPTION OF DEFECT	Regarding the engine control component of the asphalt pavers, the connection of the power relay and relay holder is not enough connection due to the inappropriate design. Therefore, if keeping using it under this situation, the engine may stop and never restart as it stops to supply the power to the injector, fuel pump, etc. by the disconnecting the relays by the running machine vibration.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
YDM—F25W5	1432W	2015~2016		25
YDN—F40W5	1741W	2015~2016		7
			TOTAL	32

(日本工業規格A列4番)