

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3757	DATE	February 9 ,2016
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>Since the inner handle of the emergency door is improperly welded, some of the strength may be inadequate. Therefore, when the handle is operated, the welded area of the handle and the link lever could come off, resulting the emergency door unable to open.</p>	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
BDG-RR7JBJ	[ISUZU GALA MIO]	2007-2010	292
BDG-RX6JFBJ	[ISUZU JOURNEY J]	2007-2010	19
		TOTAL	311