

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	3756	DATE	Feb. 9. 2016
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	Since the inner handle of the emergency door is improperly welded, some of the strength may be inadequate. Therefore, when the handle is operated, the welded area of the handle and the link lever could come off, resulting the emergency door unable to open.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-RR7JJBA	[HINO Melpha]	2007~2010	581
BDG-RX6JFBA	[HINO Liesse]	2007~2010	184
		TOTAL	765