VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Omestic Import Vehicles

CAMPAIGN No.	3755	DATE	Feb. 9. 2016	
MANUFACTURER	Hino Motors, Ltd.			
DESCRIPTION OF DEFECT	Hino Motors, Ltd. On some route buses with automatic transmission, the threaded hole processing in the torque converter cover was improper and the tightening method for bolts which fix the backing plate to the torque converter cover was improper. This may result in shortage of the axial tension of the bolts. If the bus continues to be used in this condition, the bolt may break and be caught between the torque converter cover and turbine. In the worst case, the torque converter will be locked, resulting in an engine stall, becoming unable to drive.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-KV234L2	[HINO	2010	4
PDG-KV234L2KAI	Blue Ribbon II]		
LKG-KV234L3		2011~2015	104
QDG-KV234L3			
QKG-KV234L3			
QKG-KV234L3KAI			
PJ-KV234N1		2006	1
PDG-KV234N2		2010	30
PDG-KV234N2KAI			
LDG-KV234N3		2010~2015	218
LKG-KV234N3			
LKG-KV234N3KAI			
QKG-KV234N3			
QKG-KV234N3KAI			
LKG-KV234Q3		2011~2015	62
QDG-KV234Q3			
QDG-KV234Q3KAI			
QKG-KV234Q3			
		TOTAL	419