

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3753	DATE	Feb.9.2016
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>The slide-glide door of the route bus model has a rotating shaft and a air cylinder bracket, improperly fixed with each other. The spring pin fastening the shaft and the bracket may be cracked and broken if the bus is kept in operation under such a condition. In the worst case, the spring pins on the both sides of the door will be broken, which may cause the door to open during driving, or the driver may become unable to operate the door from the driver's seat.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-KV234L1	[HINO Blue Ribbon II]	2004~2007	422
PDG-KV234L2		2007~2010	428
PKG-KV234L2		2011~2015	508
LKG-KV234L3			
QDG-KV234L3			
QKG-KV234L3			
QPG-KV234L3		2005~2007	286
PJ-KV234N1			
PDG-KV234N2		2007~2010	337
PKG-KV234N2			
LDG-KV234N3	2010~2015	530	
LKG-KV234N3			
QKG-KV234N3			
QPG-KV234N3			
		TOTAL	2,511