

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3752	DATE	February 9 ,2016
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		The slide-glide door of the route bus model has a rotating shaft and a air cylinder bracket, improperly fixed with each other. The spring pin fastening the shaft and the bracket may be cracked and broken if the bus is kept in operation under such a condition. In the worst case, the spring pins on the both sides of the door will be broken, which may cause the door to open during driving, or the driver may become unable to operate the door from the driver's seat.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-LV234L1	[ERGA]	2004-2007	748
PDG-LV234L2 PKG-LV234L2		2007-2010	775
LDG-LV234L3 LKG-LV234L3 QDG-LV234L3 QKG-LV234L3 QPG-LV234L3 QQG-LV234L3 QSG-LV234L3		2010-2016	1,104
PJ-LV234N1		2004-2007	298
PDG-LV234N2 PKG-LV234N2		2007-2010	366
LDG-LV234N3 LKG-LV234N3 QDG-LV234N3 QKG-LV234N3 QPG-LV234N3 QQG-LV234N3 QSG-LV234N3		2010-2015	736
KL-LV280L1		2000-2005	672
KL-LV280N1		2000-2005	152
KL-LV280Q1		2001-2001	4
KL-LV834L1		2000-2005	208
KL-LV834N1		2000-2004	61

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-LR233J1	[ERGA MIO] [GALA MIO]	1999-2003	33
U-LV224K	[CUBIC]	1994	1
KC-LV280L		1995-1997	23
KC-LV280N		1995-1997	7
KC-LV280Q		1997-1997	3
KC-LV380L		1996-1996	3
KC-LV832L		1998-2000	53
KC-LV832N		1998-2000	35
KL-KV280L1		[HINO BLUE RIBBON II]	2004-2005
KL-KV280N1	2004-2004		4
		TOTAL	5,327