

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3762	DATE	February 5,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	The sealant may intrude into the oil supply hole in the vacuum pump due to inappropriate installation of the vacuum pump. As a result, the insufficient oil supply may cause insufficient negative pressure due to decrease in the sealing performance of the oil film and, in the worst case, the brake pedal effort may increase resulting in longer stopping distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2016	98
		TOTAL	98