

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 7 6 1	DATE	February 8, 2016
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	In the mud system of tire roller, improper welding of mud mat fixing holder, there are things that weld strength of the joint portion of the holder is insufficient. Therefore, continuing to use as it is, it cracked at the junction due to vibration or the like during travel, in the worst case, there is a risk that mud guard device from falling on the street.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-1TZ1	「TZ701-1」	2014	38
		TOTAL	38